Executive Summary – Enforcement Matter – Case No. 50846 BASF TOTAL Petrochemicals LLC RN100216977 Docket No. 2015-1086-AIR-E

Order Type:

1660 Agreed Order

Findings Order Justification:

N/A

Media:

AIR

Small Business:

No

Location(s) Where Violation(s) Occurred:

BASF TOTAL FINA NAFTA REGION OLEFINS COMPLEX, located at Gate 99 on Farm-to-Market Road 366 at the intersection of Farm-to-Market Road 366 and State Highway 73 near Port Arthur, Jefferson County

Type of Operation:

Petrochemical plant

Other Significant Matters:

Additional Pending Enforcement Actions: No

Past-Due Penalties: No

Other: N/A

Interested Third-Parties: None

Texas Register Publication Date: November 13, 2015

Comments Received: No

Penalty Information

Total Penalty Assessed: \$32,813

Amount Deferred for Expedited Settlement: \$6,562 Amount Deferred for Financial Inability to Pay: \$0

Total Paid to General Revenue: \$13,126 Total Due to General Revenue: \$0

Payment Plan: N/A

Supplemental Environmental Project ("SEP") Conditional Offset: \$13,125

Name of SEP: Southeast Texas Regional Planning Commission (Third-Party Pre-

Approved)

Compliance History Classifications:

Person/CN - Satisfactory Site/RN - Satisfactory

Major Source: Yes

Statutory Limit Adjustment: N/A Applicable Penalty Policy: April 2014

Executive Summary – Enforcement Matter – Case No. 50846 BASF TOTAL Petrochemicals LLC RN100216977 Docket No. 2015-1086-AIR-E

Investigation Information

Complaint Date(s): N/A Complaint Information: N/A

Date(s) of Investigation: June 8, 2015

Date(s) of NOE(s): July 10, 2015

Violation Information

Failed to comply with the maximum allowable emission rate ("MAER") for the Low-Pressure Flare, Emission Point Number ("EPN") P-6. Specifically, the Respondent exceeded the volatile organic compounds ("VOC") MAER of 2.49 tons per year based on the 12-month periods ending in July 2013 through September 2014, resulting in 0.55 ton of unauthorized VOC [30 Tex. Admin. Code §§ 101.20(3), 116.115(b)(2)(F) and (c), and 122.143(4), Tex. Health & Safety Code § 382.085(b), New Source Review Permit Nos. 41945, PSD-TX-950, and N-018, Special Conditions No. 1, and Federal Operating Permit No. O2629, Special Terms and Conditions No. 14].

Corrective Actions/Technical Requirements

Corrective Action(s) Completed:

The Respondent has implemented the following corrective measures:

a. By February 27, 2014, implemented a periodic review of the flare load and updated operating procedures for the acetylene system to ensure a propylene pressure setpoint above the freezing point of water is maintained to reduce hydrate formation in the acetylene condenser, which results in high pressure and subsequent flaring to the Low-Pressure Flare, EPN P-6; and

b. On October 1, 2014, demonstrated compliance with the VOC annual MAER, based on a rolling 12-month period, for the Low-Pressure Flare, EPN P-6.

Technical Requirements:

The Order will require the Respondent to implement and complete a SEP (see SEP Attachment A).

Litigation Information

Date Petition(s) Filed: N/A Date Answer(s) Filed: N/A SOAH Referral Date: N/A Hearing Date(s): N/A

Settlement Date: N/A

Executive Summary – Enforcement Matter – Case No. 50846 BASF TOTAL Petrochemicals LLC RN100216977 Docket No. 2015-1086-AIR-E

Contact Information

TCEQ Attorney: N/A

TCEQ Enforcement Coordinator: Kingsley Coppinger, Enforcement Division, Enforcement Team 4, MC 149, (512) 239-6581; Candy Garrett, Enforcement Division,

MC 219, (512) 239-1456

TCEQ SEP Coordinator: Stuart Beckley, SEP Coordinator, Enforcement Division,

MC 219, (512) 239-3565

Respondent: Gregory Masica, Vice President - Site Manager, BASF TOTAL

PETROCHEMICALS LLC, P.O. Box 2506, Port Arthur, Texas 77642

Respondent's Attorney: N/A

Attachment A

Docket Number: 2015-1086-AIR-E

SUPPLEMENTAL ENVIRONMENTAL PROJECT

Respondent:	BASF TOTAL Petrochemicals LLC
Penalty Amount:	Twenty-Six Thousand Two Hundred Fifty-One Dollars (\$26,251)
SEP Offset Amount:	Thirteen Thousand One Hundred Twenty-Five Dollars (\$13,125)
Type of SEP:	Contribution to a Third-Party Pre-Approved SEP
Third-Party Administrator:	Southeast Texas Regional Planning Commission
Project Name:	West Port Arthur Home Energy Efficiency Program - Lighthouse Program
Location of SEP:	Jefferson County

The Texas Commission on Environmental Quality ("TCEQ") agrees to offset a portion of the administrative penalty amount assessed in this Agreed Order for the Respondent to contribute to a Supplemental Environmental Project ("SEP"). The offset is equal to the SEP Offset Amount set forth above and is conditioned upon completion of the project in accordance with the terms of this Attachment A.

1. Project Description

a. Project

The Respondent shall contribute the SEP Offset Amount to the Third-Party Administrator named above. The contribution will be to the **Southeast Texas Regional Planning Commission** for the *West Port Arthur Home Energy Efficiency Program - Lighthouse Program* Project. The contribution will be used in accordance with the SEP between the Third-Party Administrator and the TCEQ (the "Project"). Specifically, the SEP Offset Amount will be used to hire a contractor to conduct initial inspections of eligible applicants' homes. The inspections will determine whether the home is in a condition suitable for weatherization and energy efficiency upgrades. Upgrades will not be completed at homes that need new roofs or significant foundation work. The contractor shall also determine what weatherization and energy efficiency upgrades are necessary and appropriate for the home and write a work plan. This contractor shall also conduct the final inspection of the home after the work is completed.

The Third-Party Administrator will conduct eligibility determinations to verify that participants own their homes and qualify as low-income. The Third-Party Administrator will also prepare all contracts with contractors and homeowners; coordinate between the contractors and the homeowners to answer questions; ensure that work is done timely and properly; and arrange for any necessary repairs to new equipment under the 12-

month warranty period after work is completed. The SEP will be done in accordance with all federal, state, and local environmental laws and regulations.

All dollars contributed will be used for the direct cost of implementing the Project, including, but not limited to supplies, materials, and equipment. Any portion of this contribution that is not spent on the specifically identified SEP may, at the discretion of the Executive Director ("ED"), be applied to another pre-approved SEP.

The Respondent's signature affixed to this Agreed Order certifies that the Respondent has no prior commitment to make this contribution and that it is being contributed solely in an effort to settle this enforcement action. The Respondent shall not profit in any manner from this SEP.

b. Environmental Benefit

Implementation of this Project will benefit air by reducing residential fuel and electricity usage for heating and cooling. These reductions, in turn, will reduce emissions of particulate matter, volatile organic compounds, and the nitrogen oxides associated with the combustion of fuel and the generation of electricity. Past energy audits have shown a 12-30% reduction in energy usages after completion of the weatherization and energy upgrades.

c. Minimum Expenditure

The Respondent shall contribute at least the SEP Offset Amount to the Third-Party Administrator and comply with all other provisions of this SEP.

2. Performance Schedule

Within 30 days after the effective date of this Agreed Order, the Respondent must contribute the SEP Offset Amount to the Third-Party Administrator. The Respondent shall make the check payable to **Southeast Texas Regional Planning Commission SEP** and shall mail the contribution with a copy of the Agreed Order to:

Southeast Texas Regional Planning Commission Attention: Pamela Lewis, Program Manager 2210 Eastex Freeway Beaumont, Texas 77703

3. Records and Reporting

Concurrent with the payment of the SEP Offset Amount, the Respondent shall provide the Enforcement SEP Coordinator with a copy of the check and transmittal letter indicating full payment of the SEP Offset Amount to the Third-Party Administrator. The Respondent shall mail a copy of the check and transmittal letter to:

Texas Commission on Environmental Quality Enforcement Division Attention: SEP Coordinator, MC 219 P.O. Box 13087 Austin, Texas 78711-3087

4. Failure to Fully Perform

If the Respondent does not perform its obligations under this Attachment A, including full expenditure of the SEP Offset Amount and submittal of the required reporting described in Sections 2 and 3 above, the ED may require immediate payment of all or part of the SEP Offset Amount.

In the event the ED determines that the Respondent failed to fully implement and complete the Project, the Respondent shall remit payment for all or a portion of the SEP Offset Amount, as determined by the ED, and as set forth in the attached Agreed Order. After receiving notice of failure to complete the SEP, the Respondent shall include the docket number of the attached Agreed Order and a note that the enclosed payment is for the reimbursement of a SEP; shall make the check payable to "Texas Commission on Environmental Quality"; and shall mail it to:

Texas Commission on Environmental Quality Litigation Division Attention: SEP Coordinator, MC 175 P.O. Box 13087 Austin, Texas 78711-3087

5. Publicity

Any public statements concerning this SEP and/or project, made by or on behalf of the Respondent must include a clear statement that **the project was performed as part of the settlement of an enforcement action brought by the TCEQ**. Such statements include advertising, public relations, and press releases.

6. Recognition

The Respondent may not seek recognition for this contribution in any other state or federal regulatory program.

7. Other SEPs by TCEQ or Other Agencies

The SEP Offset Amount identified in this Attachment A and in the attached Agreed Order has not been, and shall not be, included as a SEP for the Respondent under any other Agreed Order negotiated with the TCEQ or any other agency of the state or federal government.

Penalty Calculation Worksheet (PCW) Policy Revision 4 (April 2014) PCW Revision March 26, 2014 Assigned 13-Jul-2015 PCW 27-Aug-2015 Screening 17-Jul-2015 EPA Due 6-Jan-2016 RESPONDENT/FACILITY INFORMATION Respondent BASF TOTAL Petrochemicals LLC Reg. Ent. Ref. No. RN100216977 Facility/Site Region 10-Beaumont Major/Minor Source Major CASE INFORMATION Enf./Case ID No. 50846 No. of Violations 1 Docket No. 2015-1086-AIR-E Order Type 1660 Media Program(s) Air Government/Non-Profit No Enf. Coordinator Rachel Bekowies Multi-Media EC's Team Enforcement Team 4 Admin. Penalty \$ Limit Minimum Maximum \$25,000

Penalty Calculation Section		
TOTAL BASE PENALTY (Sum of violation base penalties) sa	ubtotal 1	\$18,750
ADJUSTMENTS (+/-) TO SUBTOTAL 1		
Subtotals 2-7 are obtained by multiplying the Total Base Penalty (Subtotal 1) by the indicated percentage. Compliance History 100.0% Enhancement Subtotals	2, 3, & 7	\$18,750
Enhancement for two NOVs with same/similar violations, eight orders containing a denial of liability, and two orders without denial of liability. Reduction for one Notice of Intent to conduct an audit.	:	
Culpability No 0.0% Enhancement Si	ubtotal 4	\$0
Notes The Respondent does not meet the culpability criteria.		
Good Faith Effort to Comply Total Adjustments Si	ubtotal 5	-\$4,687
Economic Benefit 0.0% Enhancement* So		
Conomic Benefit O.0% Enhancement* Some standard Cost of Compliance \$2,000 Control EB & Amount Cost of Compliance \$2,000 Cost of Compliance \$2,000 Cost of	ubtotal 6	\$0
SUM OF SUBTOTALS 1-7 Final	Subtotal	\$32,813
OTHER FACTORS AS JUSTICE MAY REQUIRE 0.0% Adj Reduces or enhances the Final Subtotal by the indicated percentage.	iustment	\$0
Notes		
Final Penalty	Amount	\$32,813
STATUTORY LIMIT ADJUSTMENT Final Assessed	l Penalty	\$32,813
DEFERRAL Reduces the Final Assessed Penalty by the indicated percentage. (Enter number only; e.g. 20 for 20% reduction.)	iustment	-\$6,562
Notes Deferral offered for expedited settlement.		
PAYABLE PENALTY		\$26,251

Screening Date 17-Jul-2015

Docket No. 2015-1086-AIR-E

PCW

Policy Revision 4 (April 2014)

PCW Revision March 26, 2014

Respondent BASF TOTAL Petrochemicals LLC

Case ID No. 50846

Reg. Ent. Reference No. RN100216977

Media [Statute] Air

Enf. Coordinator Rachel Bekowies

omponent	Number of	Enter Number Here	Adjust
NOVs	Written notices of violation ("NOVs") with same or similar violations as those in the current enforcement action (number of NOVs meeting criteria)	2	10%
	Other written NOVs	0	0%
	Any agreed final enforcement orders containing a denial of liability (number of orders meeting criteria)	8	160%
Orders	Any adjudicated final enforcement orders, agreed final enforcement orders without a denial of liability, or default orders of this state or the federal government, or any final prohibitory emergency orders issued by the commission	2	50%
Judgments and Consent	Any non-adjudicated final court judgments or consent decrees containing a denial of liability of this state or the federal government (number of judgments or consent decrees meeting criteria)	0	0%
Decrees	Any adjudicated final court judgments and default judgments, or non-adjudicated final court judgments or consent decrees without a denial of liability, of this state or the federal government	0	0%
Convictions	Any criminal convictions of this state or the federal government (number of counts)	0	0%
Emissions	Chronic excessive emissions events (number of events)	0	0%
Audits	Letters notifying the executive director of an intended audit conducted under the Texas Environmental, Health, and Safety Audit Privilege Act, 74th Legislature, 1995 (number of audits for which notices were submitted)	1	-1%
	Disclosures of violations under the Texas Environmental, Health, and Safety Audit Privilege Act, 74th Legislature, 1995 (number of audits for which violations were disclosed)	0	0%
		ease Enter Yes or No	
	Environmental management systems in place for one year or more	No	0%
Other	Voluntary on-site compliance assessments conducted by the executive director under a special assistance program	No	0%
	Participation in a voluntary pollution reduction program	No	. 0%
	Early compliance with, or offer of a product that meets future state or federal government environmental requirements	No	0%
eat Violator (Adjustment Per	centage (Sub	total 2)
No		centage (Sub	total 3
pliance Histo	ory Person Classification (Subtotal 7)		
Satisfactory	Performer Adjustment Per	centage (Sub	total 7
pliance Histo	ory Summary		
Compliance History	Enhancement for two NOVs with same/similar violations, eight orders containin liability, and two orders without denial of liability. Reduction for one Notice of Inter		

Screening Date		PCW
Respondent Case ID No.	50046	licy Revision 4 (April 2014)
Reg. Ent. Reference No.	, ,	W Revision March 26, 2014
Media [Statute]		
Enf. Coordinator Violation Number	Rachel Bekowies	
Rule Cite(s)	20 T-2 A 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
	30 Tex. Admin. Code §§ 101.20(3), 116.115(b)(2)(F) and (c), and 122.143(4), Tex. Health & Safety Code § 382.085(b), New Source Review Permit Nos. 41945	. I
·	PSD-TX-950, and N-018, Special Conditions No. 1, and Federal Operating Permi	ť
	No. O2629, Special Terms and Conditions No. 14	
	Failed to comply with the maximum allowable emission rate ("MAER") for the Lov	
	Pressure Flare, Emission Point Number ("EPN") P-6. Specifically, the Respondent	
Violation Description	exceeded the volatile organic compounds ("VOC") MAER of 2.49 tons per year based on the 12-month periods ending in July 2013 through September 2014,	
	resulting in 0.55 ton of unauthorized VOC.	
,		
	Base Penal	ty \$25,000
>> Environmental, Proper	ty and Human Health Matrix	
Release	Harm Major Moderate Minor	
OR Actual	<u> </u>	
Potential	Percent 15.0%	
>>Programmatic Matrix		
Falsification	Major Moderate Minor Percent 0.0%	
	Fercent 0.0%	
Matrix Human health	or the environment has been exposed to insignificant amounts of pollutants that of	to
Notes not exceed to	evels that are protective of human health or environmental receptors as a result of the violation.	
	Adjustment \$21,25	50
		\$3,750
Violation Events		***************************************
Number of V	iolation Events 5 456 Number of violation days	The state of the s
	1 430 Number of Violation days	
	daily	
	monthly (1997)	***************************************
mark only one with an x	quarterly X Violation Base Penalt semiannual	y \$18,750
	annual	
·	single event	·
Fixe guarke]
rive qualte	rly events are recommended for the period of non-compliance from July 1, 2013 through September 30, 2014.	
Good Faith Efforts to Comp	Reduction Before NOE/NOV NOE/NOV to EDPRP/Settlement Offer	\$4,687
	Extraordinary Extraordinary	
	Ordinary X	
	N/A (mark with x)	
	The Respondent completed corrective action on October Notes 1, 2014, prior to the July 10, 2015 Notice of	Panananan
	Enforcement.	
	Violation Subtota	\$14,063
Economic Benefit (EB) for	this violation Statutory Limit Test	
	•	
Estimate	d EB Amount \$125 Violation Final Penalty Tota	
	This violation Final Assessed Penalty (adjusted for limits	\$32,813

	le '	conomic	benent	WOI	'Ksneet		
Respondent	BASF TOTAL P	etrochemicals LLC		respected and engineers			
Case ID No.	50846						
Reg. Ent. Reference No.	RN100216977	'					
Media	Air						Years of
Violation No.	1					Percent Interest	Depreciation
						5.0	1
	Thom Cock	Data Daniland	E:		.	Berry Commission Commi	15
		Date Required	Final Date	TIS	interest Saved	Onetime Costs	EB Amount
Item Description	No commas or \$						
Delayed Costs Equipment	Ir .	T T		1 0 00 T	+0	T +0	r
Equipment Buildings	 			0.00	\$0 \$0	\$0	\$0
Other (as needed)				0.00	\$0 \$0	\$0 \$0	\$0 #0
Engineering/Construction		 		0.00	\$0 \$0	\$0	\$0 \$0
Land		∤		0.00	\$0 \$0	50 n/a	\$0 \$0
Record Keeping System				0.00	\$0	n/a	\$0 \$0
Training/Sampling				0.00	\$0	n/a	\$0
				0.00	\$0	n/a	\$0
Remediation/Disposal							
Remediation/Disposal Permit Costs				0.00	\$0	n/a	\$0
	acetylene sys	tem to ensure a p	ropylene press	1.25 v of the ure setp	\$125 flare load and up oint above the fro	n/a n/a date operating proc eezing point of wate	r is maintained
Permit Costs	Estimated co acetylene sysi to reduce hy flaring to the	ist to implement a tem to ensure a p drate formation in a Low-Pressure Fla billing 12-month pe	periodic review ropylene press the acetylene ire, EPN P-6, a eriod, for the Lo	1.25 v of the ure setp condens nd to de ow-Press	\$125 flare load and up oint above the freser, which results monstrate complesure Flare, EPN P	n/a date operating processing point of wate in high pressure ar iance with the VOC -6. The Date Require	\$125 edures for the r is maintained aubsequent annual MAER,
Permit Costs Other (as needed) Notes for DELAYED costs	Estimated co acetylene sysi to reduce hy flaring to the based on a ro	ist to implement a tem to ensure a p drate formation in a Low-Pressure Fla biling 12-month pe date of non	periodic review ropylene press the acetylene are, EPN P-6, a rriod, for the Lo -compliance. T	1.25 v of the ure setp condens de to de ow-Press he final	\$125 flare load and up oint above the freser, which results monstrate compl sure Flare, EPN P Date is the date	n/a date operating proceezing point of wate in high pressure ar iance with the VOC -6. The Date Requirof compliance.	\$125 edures for the or is maintained nd subsequent annual MAER, ed is the initial
Permit Costs Other (as needed) Notes for DELAYED costs Avoided Costs	Estimated co acetylene sysi to reduce hy flaring to the based on a ro	ist to implement a tem to ensure a p drate formation in a Low-Pressure Fla biling 12-month pe date of non	periodic review ropylene press the acetylene are, EPN P-6, a rriod, for the Lo -compliance. T	1.25 v of the ure setp condens od to de pw-Presshe Final	\$125 flare load and up oint above the freser, which results monstrate compleure Flare, EPN Poute is the date gitem (except	n/a date operating proceezing point of wate in high pressure ar iance with the VOC -6. The Date Requir of compliance. for one-time avoid	\$125 edures for the er is maintained nd subsequent annual MAER, ed is the initial ded costs)
Permit Costs Other (as needed) Notes for DELAYED costs Avoided Costs Disposal	Estimated co acetylene sysi to reduce hy flaring to the based on a ro	ist to implement a tem to ensure a p drate formation in a Low-Pressure Fla biling 12-month pe date of non	periodic review ropylene press the acetylene are, EPN P-6, a rriod, for the Lo -compliance. T	1.25 v of the ure setp condens of to de to	\$125 flare load and up oint above the freser, which results monstrate complisure Flare, EPN P Date is the date gitem (except)	n/a date operating proceezing point of wate in high pressure ar iance with the VOC -6. The Date Requirof compliance. for one-time avoid	\$125 edures for the er is maintained nd subsequent annual MAER, ed is the initial ded costs) \$0
Permit Costs Other (as needed) Notes for DELAYED costs Avoided Costs Disposal Personnel	Estimated co acetylene sysi to reduce hy flaring to the based on a ro	ist to implement a tem to ensure a p drate formation in a Low-Pressure Fla biling 12-month pe date of non	periodic review ropylene press the acetylene are, EPN P-6, a rriod, for the Lo -compliance. T	1.25 v of the ure setp condens nd to de ow-Press he Final 0.00	\$125 flare load and up oint above the freser, which results monstrate complisure Flare, EPN Pote is the date gitem (except \$0 \$0 \$0	n/a date operating proceezing point of wate in high pressure ar iance with the VOC -6. The Date Requir of compliance. for one-time avoid \$0 \$0	\$125 edures for the or is maintained and subsequent annual MAER, ed is the initial ded costs) \$0 \$0
Permit Costs Other (as needed) Notes for DELAYED costs Avoided Costs Disposal Personnel spection/Reporting/Sampling	Estimated co acetylene sysi to reduce hy flaring to the based on a ro	ist to implement a tem to ensure a p drate formation in a Low-Pressure Fla biling 12-month pe date of non	periodic review ropylene press the acetylene are, EPN P-6, a rriod, for the Lo -compliance. T	v of the ure setp condens of to de ow-Press he Final enterin 0.00	\$125 flare load and up oint above the freser, which results monstrate complesure Flare, EPN Podate is the date g item (except \$0 \$0 \$0	date operating proceezing point of water in high pressure arriance with the VOC6. The Date Require of compliance. for one-time avoid \$0 \$0 \$0 \$0	\$125 edures for the or is maintained and subsequent annual MAER, ed is the initial ded costs) \$0 \$0 \$0
Permit Costs Other (as needed) Notes for DELAYED costs Avoided Costs Disposal Personnel spection/Reporting/Sampling Supplies/Equipment	Estimated co acetylene sysi to reduce hy flaring to the based on a ro	ist to implement a tem to ensure a p drate formation in a Low-Pressure Fla biling 12-month pe date of non	periodic review ropylene press the acetylene are, EPN P-6, a rriod, for the Lo -compliance. T	v of the ure setp condens of to de ow-Press he Final enterin 0.00 0.00 0.00	\$125 flare load and up oint above the friser, which results monstrate compl sure Flare, EPN P Date is the date \$0 \$0 \$0 \$0 \$0	date operating proceezing point of water in high pressure arriance with the VOC-6. The Date Require of compliance, for one-time avoid \$0 \$0 \$0 \$0 \$0	\$125 edures for the or is maintained and subsequent annual MAER, ed is the initial ded costs) \$0 \$0 \$0 \$0
Permit Costs Other (as needed) Notes for DELAYED costs Avoided Costs Disposal Personnel spection/Reporting/Sampling Supplies/Equipment Financial Assurance [2]	Estimated co acetylene sysi to reduce hy flaring to the based on a ro	ist to implement a tem to ensure a p drate formation in a Low-Pressure Fla biling 12-month pe date of non	periodic review ropylene press the acetylene are, EPN P-6, a rriod, for the Lo -compliance. T	v of the ure setp condens of to de ow-Press he Final enterin 0.00 0.00 0.00 0.00	\$125 flare load and up oint above the friser, which results monstrate complisure Flare, EPN P Date is the date gitem (except \$0 \$0 \$0 \$0 \$0 \$0	n/a date operating proceezing point of water in high pressure ariance with the VOC. 6. The Date Requirof compliance. for one-time avoid \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$125 edures for the or is maintained and subsequent annual MAER, ed is the initial ded costs) \$0 \$0 \$0 \$0 \$0 \$0
Permit Costs Other (as needed) Notes for DELAYED costs Avoided Costs Disposal Personnel spection/Reporting/Sampling Supplies/Equipment Financial Assurance [2] ONE-TIME avoided costs [3]	Estimated co acetylene sysi to reduce hy flaring to the based on a ro	ist to implement a tem to ensure a p drate formation in a Low-Pressure Fla biling 12-month pe date of non	periodic review ropylene press the acetylene are, EPN P-6, a rriod, for the Lo -compliance. T	v of the ure setp condens of to de ow-Press he Final enterin 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.	\$125 flare load and up oint above the freser, which results monstrate complisure Flare, EPN P Date is the date gitem (except \$0 \$0 \$0 \$0 \$0 \$0 \$0	n/a date operating proceeding point of water in high pressure ariance with the VOC. 6. The Date Require of compliance. for one-time avoid \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$125 edures for the or is maintained and subsequent annual MAER, ed is the initial ded costs) \$0 \$0 \$0 \$0 \$0 \$0 \$0
Permit Costs Other (as needed) Notes for DELAYED costs Avoided Costs Disposal Personnel spection/Reporting/Sampling Supplies/Equipment Financial Assurance [2] ONE-TIME avoided costs [3] Other (as needed)	Estimated co acetylene sysi to reduce hy flaring to the based on a ro	ist to implement a tem to ensure a p drate formation in a Low-Pressure Fla biling 12-month pe date of non	periodic review ropylene press the acetylene are, EPN P-6, a rriod, for the Lo -compliance. T	v of the ure setp condens of to de ow-Press he Final enterin 0.00 0.00 0.00 0.00	\$125 flare load and up oint above the friser, which results monstrate complisure Flare, EPN P Date is the date gitem (except \$0 \$0 \$0 \$0 \$0 \$0	n/a date operating proceezing point of water in high pressure ariance with the VOC. 6. The Date Requirof compliance. for one-time avoid \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$125 edures for the or is maintained and subsequent annual MAER, ed is the initial ded costs) \$0 \$0 \$0 \$0 \$0 \$0
Permit Costs Other (as needed) Notes for DELAYED costs Avoided Costs Disposal Personnel aspection/Reporting/Sampling Supplies/Equipment Financial Assurance [2] ONE-TIME avoided costs [3]	Estimated co acetylene sysi to reduce hy flaring to the based on a ro	ist to implement a tem to ensure a p drate formation in a Low-Pressure Fla biling 12-month pe date of non	periodic review ropylene press the acetylene are, EPN P-6, a rriod, for the Lo -compliance. T	v of the ure setp condens of to de ow-Press he Final enterin 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.	\$125 flare load and up oint above the freser, which results monstrate complisure Flare, EPN P Date is the date gitem (except \$0 \$0 \$0 \$0 \$0 \$0 \$0	n/a date operating proceeding point of water in high pressure ariance with the VOC. 6. The Date Require of compliance. for one-time avoid \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$125 edures for the or is maintained and subsequent annual MAER, ed is the initial ded costs) \$0 \$0 \$0 \$0 \$0 \$0



Compliance History Report

PUBLISHED Compliance History Report for CN604166967, RN100216977, Rating Year 2014 which includes Compliance History (CH) components from September 1, 2009, through August 31, 2014.

Customer, Respondent,

CN604166967, BASF TOTAL

Classification: SATISFACTORY

Rating: 20.47

or Owner/Operator:

Petrochemicals LLC

Rating: 20.47

Regulated Entity:

REGION OLEFINS COMPLEX

RN100216977, BASF TOTAL FINA NAFTA Classification: SATISFACTORY

Rating Date: 09/01/2014

Complexity Points:

Repeat Violator: NO

CH Group:

05 - Chemical Manufacturing

Location:

AT GATE 99 ON FARM-TO-MARKET ROAD 366, AT THE INTERSECTION OF FARM-TO-MARKET ROAD 366 AND

STATE HIGHWAY 73, NEAR PORT ARTHUR, TEXAS, JEFFERSON COUNTY

TCEQ Region:

REGION 10 - BEAUMONT

ID Number(s):

AIR OPERATING PERMITS ACCOUNT NUMBER JE0843F

AIR OPERATING PERMITS PERMIT 2629

WASTEWATER PERMIT WQ0004135000

INDUSTRIAL AND HAZARDOUS WASTE EPA ID

TXR000039909

AIR NEW SOURCE PERMITS AFS NUM 4824500182

AIR NEW SOURCE PERMITS ACCOUNT NUMBER JE0843F

AIR NEW SOURCE PERMITS PERMIT 41945

AIR NEW SOURCE PERMITS EPA PERMIT NO18

AIR NEW SOURCE PERMITS EPA PERMIT N007M1

AIR NEW SOURCE PERMITS EPA PERMIT PSDTX903M2

AIR NEW SOURCE PERMITS REGISTRATION 79052

AIR NEW SOURCE PERMITS REGISTRATION 81912

AIR NEW SOURCE PERMITS REGISTRATION 84227

AIR NEW SOURCE PERMITS REGISTRATION 109112

AIR NEW SOURCE PERMITS EPA PERMIT NO18M2

AIR NEW SOURCE PERMITS REGISTRATION 95473

AIR NEW SOURCE PERMITS REGISTRATION 101222 AIR NEW SOURCE PERMITS REGISTRATION 97972

AIR NEW SOURCE PERMITS REGISTRATION 100060

AIR NEW SOURCE PERMITS REGISTRATION 101918

AIR NEW SOURCE PERMITS REGISTRATION 103760

AIR NEW SOURCE PERMITS REGISTRATION 118750

AIR NEW SOURCE PERMITS REGISTRATION 118986 AIR NEW SOURCE PERMITS REGISTRATION 120275

AIR NEW SOURCE PERMITS REGISTRATION 124227

AIR NEW SOURCE PERMITS REGISTRATION 133393

AIR NEW SOURCE PERMITS REGISTRATION 119760

AIR NEW SOURCE PERMITS REGISTRATION 125108

AIR NEW SOURCE PERMITS EPA PERMIT GHGPSDTX3

AIR NEW SOURCE PERMITS REGISTRATION 109102

AIR NEW SOURCE PERMITS REGISTRATION 131427

AIR NEW SOURCE PERMITS REGISTRATION 111865

AIR EMISSIONS INVENTORY ACCOUNT NUMBER JE0843F

Compliance History Period: September 01, 2009 to August 31, 2014

Date Compliance History Report Prepared: July 14, 2015

Agency Decision Requiring Compliance History:

Component Period Selected:

July 14, 2010 to July 14, 2015

AIR OPERATING PERMITS PERMIT 2551

POLLUTION PREVENTION PLANNING ID NUMBER

P06698

WASTEWATER EPA ID TX0119369

INDUSTRIAL AND HAZARDOUS WASTE SOLID WASTE

REGISTRATION # (SWR) 86596

AIR NEW SOURCE PERMITS PERMIT 36644

AIR NEW SOURCE PERMITS EPA PERMIT PSDTX950

AIR NEW SOURCE PERMITS EPA PERMIT NO07

AIR NEW SOURCE PERMITS EPA PERMIT PSDTX903

AIR NEW SOURCE PERMITS REGISTRATION 76480

AIR NEW SOURCE PERMITS EPA PERMIT PSDTX903M1

AIR NEW SOURCE PERMITS REGISTRATION 82105

AIR NEW SOURCE PERMITS EPA PERMIT PSDTX903M3

AIR NEW SOURCE PERMITS EPA PERMIT NO18M1

AIR NEW SOURCE PERMITS EPA PERMIT PSDTX903M4

AIR NEW SOURCE PERMITS EPA PERMIT PSDTX903M5

AIR NEW SOURCE PERMITS REGISTRATION 96596

AIR NEW SOURCE PERMITS REGISTRATION 97023

AIR NEW SOURCE PERMITS REGISTRATION 100466

AIR NEW SOURCE PERMITS REGISTRATION 100331

AIR NEW SOURCE PERMITS REGISTRATION 103757

AIR NEW SOURCE PERMITS REGISTRATION 107198

AIR NEW SOURCE PERMITS REGISTRATION 107854

AIR NEW SOURCE PERMITS REGISTRATION 129877

AIR NEW SOURCE PERMITS REGISTRATION 120771

AIR NEW SOURCE PERMITS REGISTRATION 110943 AIR NEW SOURCE PERMITS REGISTRATION 113825

AIR NEW SOURCE PERMITS REGISTRATION 122891

AIR NEW SOURCE PERMITS REGISTRATION 126179

AIR NEW SOURCE PERMITS REGISTRATION 109680

AIR NEW SOURCE PERMITS REGISTRATION 114757

AIR NEW SOURCE PERMITS REGISTRATION 107230

Rating Year: 2014

AIR NEW SOURCE PERMITS REGISTRATION 113001

TCEQ Staff Member to Contact for Additional Information Regarding This Compliance History.

Name: Rachel Bekowies Phone: (512) 239-2608

Site and Owner/Operator History:

1) Has the site been in existence and/or operation for the full five year compliance period? YES

2) Has there been a (known) change in ownership/operator of the site during the compliance period? NO

3) If **YES** for #2, who is the current owner/operator? N/A

N/A

4) If YES for #2, who was/were the prior owner(s)/operator(s)?

5) If **YES**, when did the change(s) in owner or operator N/A occur?

Components (Multimedia) for the Site Are Listed in Sections A - J

A. Final Orders, court judgments, and consent decrees:

Effective Date: 08/09/2010 ADMINORDER 2010-0137-AIR-E (1660 Order-Agreed Order With Denial)

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(2)

30 TAC Chapter 113, SubChapter C 113.110

40 CFR Chapter 63, SubChapter C, PT 63, SubPT F 63.104(a)

5C THSC Chapter 382 382.085(b)

Description: Failed to monitor the heat exchange system (cooling tower) properly to detect for leaks of hazardous air

ADMINORDER 2010-0393-AIR-E (1660 Order-Agreed Order With Denial)

pollutants.

2

Effective Date: 09/26/2010 Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rgmt Prov: 36644/PSD-TX-903M2, Special Condition 1 PERMIT

O-02965, General Terms and Conditions OP

O-02965, Special Condition 6A OP

Description: Failure to maintain the Carbon Monoxide (CO) and Nitrogen Oxides (NOx) emission rates at Boiler B-7280.

Emission Point Number (EPN) N-24A, below the allowable emission limits.

3 Effective Date: 04/18/2011 ADMINORDER 2010-1318-AIR-E (1660 Order-Agreed Order With Denial)

Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter C 115.241

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov: O-02551, General Terms and Conditions OP

Description: Failure to transfer or allow the transfer of gasoline from any stationary storage container into a motor vehicle

fuel tank with an approved Stage II vapor recovery system.

Classification: Moderate

30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rgmt Prov: 36644/PSD-TX-903M2, Special Condition 1 PERMIT

O-02551, General Terms and Conditions OP

O-02551, Special Condition 11A OP

Description: Failure to maintain the NOx emission rate at Cogeneration Train Unit 2 (EPN: N-20B) below the allowable

emission limit.

Classification: Moderate

30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rgmt Prov: 36644/PSD-TX-903M2, Special Condition 1 PERMIT

O-02551, General Terms and Conditions OP

O-02551, Special Condition 11A OP

Description: Failure to maintain the NOx and CO emission rates at Fresh Feed Cracking Furnace H-0900 (EPN: N-9) below

the allowable emission limits.

4 Effective Date: 07/31/2011

ADMINORDER 2011-0073-AIR-E (1660 Order-Agreed Order With Denial)

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov: 41945, PSD-TX-950, SC 1 PERMIT

0-02629 GTC and SC8 OP

Description: Failed to maintain an emission rate below the MAER for VOC from the Low Pressure Flare (Emission Point Number P-6). Specifically, the Respondent exceeded the rolling 12-month MAER of 2.17 tons for VOC from April 2009 through February 2010, resulting in the unauthorized release of 4.03 tons of VOC.

Effective Date: 05/25/2012

ADMINORDER 2011-1403-AIR-E (1660 Order-Agreed Order With Denial)

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov: 36644/PSD-TX-903M3, SC 1 PERMIT

Special Conditions No. 1 PERMIT

Special Terms and Conditions No. 20 OP

Description: Failed to maintain compliance with NOx hourly MAER for Heater H-0900. Specifically, the heater exceeded the NOx MAER of 12.19 pounds per hour ("lb/hr") for a total of 48 hours on November 26 and 27, 2010, and February 17, 2011. The NOx emission rate ranged from 13.99 lb/hr to 19.21 lb/hr.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov: 36644/PSD-TX-903M3, SC30C PERMIT

SC No. 30.C. PERMIT

STC No. 20 OP

Description: Failed to use the correct reference temperature to determine the stack flow concentration based on the measured firing rate and British thermal unit ("Btu") content of the fuel for the following units (and Emission Point Nos.): Ethylene Cracking Furnaces (N-1 through N-9), Supplemental Boiler (N-14), the Cogeneration Trains (N-20A and N-20B), Boilers B-7280 (N-24) and B-7290 (N-24B), and the Thermal Oxidizer (N-19). The Respondent used a temperature of 60EF instead of the standard of 68EF to co

6 Effective Date: 04/07/2013

ADMINORDER 2012-1277-AIR-E (1660 Order-Agreed Order With Denial)

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov: 36644, Special Condition 1 PERMIT

O-02551, Special Condition 20 OP

Description: Failed to maintain compliance with the NOx hourly MAER for Boiler B-7290 (Emission Point No. N-24B). Specifically, Boiler B-7290 exceeded the NOx MAER of 4.25 lbs/hr on May 16, 2011 for four hours and on July 29, 2011 for one hour. The NOx emission rate ranged from 5.05 lbs/hr to 20.36 lbs/hr.

Effective Date: 08/26/2013
Classification: Major

Citation: 2D TWC Chapter 26, SubChapter A 26.121(a)(1)

30 TAC Chapter 305, SubChapter F 305.125(1)

Rqmt Prov: Permit Conditions No. 2.d PERMIT

Description: Failed to prevent the unauthorized discharge of industrial wastewater. During an investigation on May 25, 2012, TCEQ staff documented that approximately 1,190,000 gallons of water containing 785 pounds of free chlorine was discharged from the storm water pond, which is authorized to discharge only non-process area storm water runoff. The discharge went through Outfall No. 001 into Drainage District ("DD") 7 Lateral 1-A to the confluence of DD-7 Lateral 1-A with the DD-7 Atlantic Main Ditch r

8 Effective Date: 08/15/2014

ADMINORDER 2013-1835-AIR-E (Findings Order-Agreed Order Without Denial)

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov: 36644 - SC1 PERMIT

O-02551 - SC24A OP

Description: Failed to comply with the MAER of 17.65 lbs/hr of NOx for Cogeneration Unit 2, EPN N-20B.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov: 36644, SC 14 PERMIT

O-02551, SC24A OP

Description: Failed to maintain the minimum net heating value for the Shielded Flare, EPN N-15A, and the Ground Flare,

EPN N-15.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov: SC1 PERMIT

SC24A OP

Description: Failed to comply with the MAER of 13.60 lbs/hr of NOx for Boiler B-7240, EPN N-14.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Ramt Prov: SC1 PERMIT

SC24A OP

Description: Failed to comply with the MAER for the Flare System, EPNs N-15 and N-15A

Effective Date: 08/22/2014

ADMINORDER 2014-0303-AIR-E (1660 Order-Agreed Order With Denial)

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rgmt Prov: Special Condition 1 PA

Special Condition 1 PERMIT Special Condition 24 A OP

Description: Failed to prevent unauthorized emissions. Specifically, the Respondent released 101.99 pounds ("lbs") of VOC from the Thermal Oxidizer, EPN N-19, during an emissions event (Incident No. 186234) that began on August 1, 2013 and lasted five hours and twenty minutes. The emissions event occurred when the Thermal Oxidizer interlocked due to the introduction of liquid VOC fuel; the interlock caused the fuel gas valve to close automatically but the process streams were routed to the Thermal Oxidizer.

10

Effective Date: 05/07/2015
Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov: SC 1 PERMIT

SC 23 OP

Description: Failed to prevent unauthorized emissions. Specifically, the Respondent released 256.49 pounds of volatile organic compounds from Emissions Point Number F-1, during an emissions event (Incident No. 197978) that occurred on May 7, 2014 and lasted five minutes. The emissions event occurred due to a leak at the suction strainer on the medium gasoline pump from the Charge Gas Compressor 2nd Stage.

B. Criminal convictions:

N/A

C. Chronic excessive emissions events:

July 31, 2010

N/Δ

D. The approval dates of investigations (CCEDS Inv. Track. No.):

item i	July 31, 2010	(829467)
Item 2	September 03, 2010	(849157)
Item 3	September 16, 2010	(864368)
Item 4	September 29, 2010	(849057)
Item 5	November 30, 2010	(877275)
Item 6	February 28, 2011	(899069)
Item 7	May 06, 2011	(915541)
Item 8	July 19, 2011	(921694)
Item 9	September 12, 2011	(951981)
Item 10	October 13, 2011	(949970)
Item 11	February 28, 2012	(983111)
Item 12	May 16, 2012	(1002244)
Item 13	September 18, 2012	(1031377)
Item 14	October 17, 2012	(1035687)
Item 15	October 29, 2012	(1034663)
Item 16	November 20, 2012	(1044058)
Item 17	November 30, 2012	(1043017)
Item 18	January 04, 2013	(1051857)
Item 19	February 05, 2013	(1043769)
Item 20	May 07, 2013	(1074674)
Item 21	May 13, 2013	(1088762)
Item 22	July 01, 2013	(1099043)
Item 23	February 03, 2014	(1144480)
Item 24	February 06, 2014	(1145006)
Item 25	May 27, 2014	(1166067)
Item 26	August 22, 2014	(1190425)
Item 27	September 15, 2014	(1086701)
Item 28	September 16, 2014	(1196081)
Item 29	May 04, 2015	(1247918)
Item 30	May 29, 2015	(1248203)
Item 31	June 04, 2015	(1254649)
Item 32	July 09, 2015	(1261660)

E. Written notices of violations (NOV) (CCEDS Inv. Track. No.):

A notice of violation represents a written allegation of a violation of a specific regulatory requirement from the commission to a regulated entity. A notice of violation is not a final enforcement action, nor proof that a violation has actually occurred.

1 Date: 08/22/2014 (1184680) Self Report? NO CN604166967

Classification: Minor

Citation:

30 TAC Chapter 101, SubChapter A 101.20(1)

```
30 TAC Chapter 101, SubChapter A 101.20(3)
                30 TAC Chapter 115, SubChapter D 115.352(4)
                30 TAC Chapter 122, SubChapter B 122.143(4)
                40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-6(a)(1)
                5C THSC Chapter 382 382.085(b)
                General Terms and Conditions OP
                SC 1A OP
                SC 2D PERMIT
                SC 34 PERMIT
                Special Condition (SC) 14 OP
Description:
                Failure to prevent open-ended line or valve without a cap, plug, second valve, or
                blind flange on one component.
Self Report?
                                                          Classification:
                                                                           Moderate
                30 TAC Chapter 101, SubChapter A 101.20(1)
Citation:
                30 TAC Chapter 101, SubChapter A 101.20(3)
                30 TAC Chapter 115, SubChapter D 115.354(11)
                30 TAC Chapter 115, SubChapter D 115.354(2)
                30 TAC Chapter 116, SubChapter B 116.115(c)
                30 TAC Chapter 122, SubChapter B 122.143(4)
                40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.163(b)(1)
                40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(b)
                40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(a)(1)
                5C THSC Chapter 382 382.085(b)
                General Terms and Conditions OP
               SC 14 OP
                SC 1A OP
                SC 9E, 9F, and 9G PERMIT
               Failure to conduct quarterly fugitive monitoring of 40 components.
Description:
Self Report?
                                                          Classification:
                                                                           Moderate
Citation:
                30 TAC Chapter 101, SubChapter A 101.20(3)
                30 TAC Chapter 116, SubChapter B 116.116(b)(1)
                30 TAC Chapter 122, SubChapter B 122.143(4)
                5C THSC Chapter 382 382.085(b)
               General Terms and Conditions OP
Description:
                Failure to permit 40 components in VOC service.
Self Report?
                                                          Classification:
                                                                           Moderate
Citation:
               30 TAC Chapter 122, SubChapter B 122.143(4)
                30 TAC Chapter 122, SubChapter B 122.145(2)(A)
                30 TAC Chapter 122, SubChapter B 122.146(5)(D)
                5C THSC Chapter 382 382.085(b)
                General Conditions OP
Description:
               Failure to report one deviation in a Semiannual Deviation Report.
Self Report?
                                                          Classification:
                                                                           Moderate
Citation:
                30 TAC Chapter 122, SubChapter B 122.143(4)
                30 TAC Chapter 122, SubChapter B 122.146(1)
                5C THSC Chapter 382 382.085(b)
                General Conditions OP
Description:
                Failure to accurately certify compliance in the Annual Certification for the periods
               ending February 28, 2013 and February 28, 2014.
Self Report?
                                                          Classification:
                                                                           Moderate
Citation:
                30 TAC Chapter 116, SubChapter B 116,115(c)
                30 TAC Chapter 122, SubChapter B 122.143(4)
               5C THSC Chapter 382 382.085(b)
               General Terms and Conditions OP
               SC 14 OP
               SC 19D(1) PERMIT
Description:
               Failure to perform Audio, visual, olfactory (AVO) check for Ammonia leaks.
Self Report?
              NO
                                                          Classification:
                                                                          Moderate
Citation:
               30 TAC Chapter 101, SubChapter A 101.20(3)
                30 TAC Chapter 116, SubChapter B 116.115(c)
               30 TAC Chapter 122, SubChapter B 122.143(4)
               5C THSC Chapter 382 382.085(b)
               General Terms and Conditions OP
               SC 14 OP
               SC 16 PERMIT
Description:
               Failure to comply with the permitted CO and NOx limits.
Self Report?
                                                          Classification:
                                                                          Moderate
Citation:
               30 TAC Chapter 122, SubChapter B 122.143(4)
               30 TAC Chapter 122, SubChapter C 122.210(a)
               30 TAC Chapter 122, SubChapter C 122.217(a)(2)
               5C THSC Chapter 382 382.085(b)
               General Terms and Conditions OP
Description:
               Failure to submit a permit revision application prior to operating a change.
```

Self Report? Classification: Moderate Citation: 30 TAC Chapter 101, SubChapter A 101.20(3) 30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4) 5C THSC Chapter 382 382.085(b) General Term and Conditions OP SC 21 PERMIT SC 24A OP Description: Failure to comply with the permitted CO and NOx limits. Self Report? Classification: Moderate Citation: 30 TAC Chapter 122, SubChapter B 122.143(4) 30 TAC Chapter 122, SubChapter B 122.145(2)(A) 30 TAC Chapter 122, SubChapter B 122.146(5)(D) General Conditions OP Description: Failure to report 5 deviations in a Semiannual Devition Report. Self Report? NO Classification: Moderate Citation: 30 TAC Chapter 122, SubChapter B 122.143(4) 30 TAC Chapter 122, SubChapter B 122.146(1) 30 TAC Chapter 122, SubChapter B 122.146(5)(D) General Conditions OP Failure to accurately certify compliance in the Annual Compliance Certification for Description: the period ending February 28, 2013. Self Report? Classification: Moderate Citation: 30 TAC Chapter 101, SubChapter A 101.20(1) 30 TAC Chapter 115, SubChapter D 115.352(4) 30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4) 40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-6(a)(1) 5C THSC Chapter 382 382.085(b) General Terms and Conditions OP SC 1A OP SC 24A OP SC 4B PERMIT SC 9E PERMIT Description: Failure to prevent open-ended lines or valves without a cap, plug, second valve, or blind flange on 3 components. Self Report? Classification: Moderate Citation: 30 TAC Chapter 115, SubChapter D 115.354(11) 30 TAC Chapter 115, SubChapter D 115.354(2)(C) 30 TAC Chapter 116, SubChapter B 116.115(c) 40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-2(a)(1) 40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-7(a)(1) General Terms and Conditions OP SC 10 PERMIT SC 1A OP SC 24A OP SC 4B PERMIT SC 9E, 9F and 9G PERMIT Description: Failure to conduct quarterly fugitive monitoring of 1850 components in VOC service. Self Report? Classification: Moderate Citation: 30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4) 5C THSC Chapter 382 382.085(b) General Terms and Conditions OP SC 24 OP SC 25 PERMIT Description: Failure to analyze a cooling tower bag sample within 72 hours. Self Report? Classification: Moderate Citation: 30 TAC Chapter 101, SubChapter A 101.20(3) 30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4) 5C THSC Chapter 382 382.085(b) General Terms and Conditions OP SC 16A PERMIT Failure to comply with the permitted NOx parts per million (ppmvd) of 6 ppmvd Description:

for Cogeneration Unit 2 for a total of 26 hours. Self Report? Classification: Moderate 30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

Citation:

5C THSC Chapter 382 382.085(b) General Terms and Conditions OP SC 21E PERMIT SC 24A OP

Description: Failure to comply with permitted NH3 ppmvd limits.

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b) General Terms and Conditions OP

SC 19 PERMIT SC 24A OP

Description: Failure to maintain the Thermal Oxidizer operating temperature above the

minimum on three occassions.

Self Report? NO Citation: 30 TAC Char

O Classification: Moderate 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b) General Terms and Conditions OP

SC 20A PERMIT SC 24A OP

Description: Self Report? N

Failure to monitor the Carbon Adsorption System (CAS) on two occassions.

O Classification: Moderate

Citation:

30 TAC Chapter 101, SubChapter A 101.20(3) 30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(3)(ii) 40 CFR Chapter 63, SubChapter C, PT 63, SubPT A 63.11(b)(6)(ii)

5C THSC Chapter 382 382.085(b) General Terms and Conditions OP

SC 14 PERMIT SC 1A OP SC 24A OP

Description:

Failure to maintain the minimum BTU/scf requirements for the vent gas being

Major

Moderate

Moderate

vented to the flare system.

Self Report?

Citation:

? NO Classification: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 101, SubChapter A 101.20(3)
30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b) General Terms and Conditions OP

SC 1 PERMIT SC 24A OP

Description:

Citation:

Failure to comply with the emissions specified in SC 1 of Permit 36644. However, this exceedance was less than 1% of the operating period, and therefore is not

significant.

Data

2

Date: 07/10/2015 (1258843)

CN604166967

Classification:

Self Report? NO

30 TAC Chapter 122, SubChapter B 122.143(4) 30 TAC Chapter 122, SubChapter B 122.145(2)(A)

30 TAC Chapter 122, SubChapter B 122.146(5)(D)

5C THSC Chapter 382 382.085 General Terms and Conditions OP

Special Condition 17 OP

Description: F

Failure to report all instances of deviations.

Self Report? NO Classification:

Citation: 30 TAC Char

30 TAC Chapter 101, SubChapter A 101.20(1) 30 TAC Chapter 115, SubChapter D 115.352(2) 30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-7(d)(1)

5C THSC Chapter 382 382.085(b)

SC 14 OP SC 1A OP SC 2D PERMIT SC 9H PERMIT

Description: Failure to complete repair of a leaking component within 15 days.

F. Environmental audits:

Notice of Intent Date: 06/08/2011 (934631)

No DOV Associated

G. Type of environmental management systems (EMSs):

N/A

H. Voluntary on-site compliance assessment dates:

I. Participation in a voluntary pollution reduction program:

J. Early compliance:

N/A

Sites Outside of Texas:

N/A

Texas Commission on Environmental Quality



IN THE MATTER OF AN	Š	BEFORE THE
ENFORCEMENT ACTION	§	
CONCERNING	§	THE VAC CONTACTOR ON ON
BASF TOTAL PETROCHEMICALS	§	TEXAS COMMISSION ON
LLC	§	
RN100216977	§	ENVIRONMENTAL QUALITY

AGREED ORDER DOCKET NO. 2015-1086-AIR-E

I. JURISDICTION AND STIPULATIONS

On ________, the Texas Commission on Environmental Quality ("the Commission" or "TCEQ") considered this agreement of the parties, resolving an enforcement action regarding BASF TOTAL Petrochemicals LLC ("Respondent") under the authority of TEX. HEALTH & SAFETY CODE ch. 382 and TEX. WATER CODE ch. 7. The Executive Director of the TCEQ, through the Enforcement Division, and the Respondent together stipulate that:

- 1. The Respondent owns and operates a petrochemical plant located at Gate 99 on Farm-to-Market Road 366, at the intersection of Farm-to-Market Road 366 and State Highway 73, near Port Arthur, Jefferson County, Texas (the "Plant").
- 2. The Plant consists of one or more sources as defined in Tex. HEALTH & SAFETY CODE \$382.003(12).
- 3. The Executive Director and the Respondent agree that the Commission has jurisdiction to enter this Agreed Order, and that the Respondent is subject to the Commission's jurisdiction.
- 4. The Respondent received notice of the violations alleged in Section II ("Allegations") on or about July 15, 2015.
- 5. The occurrence of any violation is in dispute and the entry of this Agreed Order shall not constitute an admission by the Respondent of any violation alleged in Section II ("Allegations"), nor of any statute or rule.
- 6. An administrative penalty in the amount of Thirty-Two Thousand Eight Hundred Thirteen Dollars (\$32,813) is assessed by the Commission in settlement of the violations

alleged in Section II ("Allegations"). The Respondent has paid Thirteen Thousand One Hundred Twenty-Six Dollars (\$13,126) of the administrative penalty and Six Thousand Five Hundred Sixty-Two Dollars (\$6,562) is deferred contingent upon the Respondent's timely and satisfactory compliance with all the terms of this Agreed Order. The deferred amount will be waived upon full compliance with the terms of this Agreed Order. If the Respondent fails to timely and satisfactorily comply with all requirements of this Agreed Order, the Executive Director may require the Respondent to pay all or part of the deferred penalty. Thirteen Thousand One Hundred Twenty-Five Dollars (\$13,125) shall be conditionally offest by the Respondent's completion of a Supplemental Environmental Project ("SEP").

- 7. Any notice and procedures, which might otherwise be authorized or required in this action, are waived in the interest of a more timely resolution of the matter.
- 8. The Executive Director and the Respondent agree on a settlement of the matters alleged in this enforcement action, subject to final approval in accordance with 30 Tex. ADMIN. CODE § 70.10(a).
- 9. The Executive Director recognizes that the Respondent has implemented the following corrective measures at the Plant:
 - a. By February 27, 2014, implemented a periodic review of the flare load and updated operating procedures for the acetylene system to ensure a propylene pressure setpoint above the freezing point of water is maintained to reduce hydrate formation in the acetylene condenser, which results in high pressure and subsequent flaring to the Low-Pressure Flare, Emission Point Number ("EPN") P-6; and
 - b. On October 1, 2014, demonstrated compliance with the volatile organic compounds ("VOC") annual maximum allowable emission rate ("MAER"), based on a rolling 12-month period, for the Low-Pressure Flare, EPN P-6.
- 10. The Executive Director may, without further notice or hearing, refer this matter to the Office of the Attorney General of the State of Texas ("OAG") for further enforcement proceedings if the Executive Director determines that the Respondent has not complied with one or more of the terms or conditions in this Agreed Order.
- 11. This Agreed Order shall terminate five years from its effective date or upon compliance with all the terms and conditions set forth in this Agreed Order, whichever is later.
- 12. The provisions of this Agreed Order are deemed severable and, if a court of competent jurisdiction or other appropriate authority deems any provision of this Agreed Order unenforceable, the remaining provisions shall be valid and enforceable.

II. ALLEGATIONS

As owner and operator of the Plant, the Respondent is alleged to have failed to comply with the MAER for the Low-Pressure Flare, EPN P-6, in violation of 30 Tex. Admin. Code §§ 101.20(3), 116.115(b)(2)(F) and (c), and 122.143(4), Tex. Health & Safety Code § 382.085(b), New Source Review Permit Nos. 41945, PSD-TX-950, and N-018, Special Conditions No. 1, and Federal Operating Permit No. O2629, Special Terms and Conditions No. 14, as documented during a record review conducted on June 8, 2015. Specifically, the Respondent exceeded the VOC MAER of 2.49 tons per year based on the 12-month periods ending in July 2013 through September 2014, resulting in 0.55 ton of unauthorized VOC.

III. DENIALS

The Respondent generally denies each allegation in Section II ("Allegations").

IV. ORDERING PROVISIONS

1. It is, therefore, ordered by the TCEQ that the Respondent pay an administrative penalty as set forth in Section I, Paragraph 6 above. The payment of this administrative penalty and the Respondent's compliance with all the terms and conditions set forth in this Agreed Order resolve only the allegations in Section II. The Commission shall not be constrained in any manner from requiring corrective action or penalties for violations which are not raised here. Administrative penalty payments shall be made payable to "TCEQ" and shall be sent with the notation "Re: BASF TOTAL Petrochemicals LLC, Docket No. 2015-1086-AIR-E" to:

Financial Administration Division, Revenue Operations Section Attention: Cashier's Office, MC 214 Texas Commission on Environmental Quality P.O. Box 13088 Austin, Texas 78711-3088

- 2. The Respondent shall implement and complete a SEP in accordance with Tex. WATER CODE § 7.067. As set forth in Section I, Paragraph 6 above, Thirteen Thousand One Hundred Twenty-Five Dollars (\$13,125) of the assessed administrative penalty shall be offset with the condition that the SEP defined in Attachment A, incorporated herein by reference, is implemented by the Respondent. The Respondent's obligation to pay the conditionally offset portion of the assessed administrative penalty shall be discharged upon final completion of all provisions of the SEP agreement.
- 3. The provisions of this Agreed Order shall apply to and be binding upon the Respondent. The Respondent is ordered to give notice of the Agreed Order to personnel who maintain day-to-day control over the Plant operations referenced in this Agreed Order.

- 4. If the Respondent fails to comply with any of the Ordering Provisions in this Agreed Order within the prescribed schedules, and that failure is caused solely by an act of God, war, strike, riot, or other catastrophe, the Respondent's failure to comply is not a violation of this Agreed Order. The Respondent shall have the burden of establishing to the Executive Director's satisfaction that such an event has occurred. The Respondent shall notify the Executive Director within seven days after the Respondent becomes aware of a delaying event and shall take all reasonable measures to mitigate and minimize any delay.
- 5. The Executive Director may grant an extension of any deadline in this Agreed Order or in any plan, report, or other document submitted pursuant to this Agreed Order, upon a written and substantiated showing of good cause. All requests for extensions by the Respondent shall be made in writing to the Executive Director. Extensions are not effective until the Respondent receives written approval from the Executive Director. The determination of what constitutes good cause rests solely with the Executive Director.
- 6. This Agreed Order, issued by the Commission, shall not be admissible against the Respondent in a civil proceeding, unless the proceeding is brought by the OAG to: (1) enforce the terms of this Agreed Order; or (2) pursue violations of a statute within the Commission's jurisdiction, or of a rule adopted or an order or permit issued by the Commission under such a statute.
- This Agreed Order may be executed in separate and multiple counterparts, which 7. together shall constitute a single instrument. Any page of this Agreed Order may be copied, scanned, digitized, converted to electronic portable document format ("pdf"), or otherwise reproduced and may be transmitted by digital or electronic transmission, including but not limited to facsimile transmission and electronic mail. Any signature affixed to this Agreed Order shall constitute an original signature for all purposes and may be used, filed, substituted, or issued for any purpose for which an original signature could be used. The term "signature" shall include manual signatures and true and accurate reproductions of manual signatures created, executed, endorsed, adopted, or authorized by the person or persons to whom the signatures are attributable. Signatures may be copied or reproduced digitally, electronically, by photocopying, engraving, imprinting, lithographing, electronic mail, facsimile transmission, stamping, or any other means or process which the Executive Director deems acceptable. In this paragraph exclusively, the terms "electronic transmission", "owner", "person", "writing", and "written" shall have the meanings assigned to them under TEX. BUS. ORG. CODE § 1.002.
- 8. The effective date of this Order is the date it is signed by the Commission. A copy of this fully executed Order shall be provided to each of the parties.

For the Commission

SIGNATURE PAGE

Date

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

Porthe Executive Director	
agree to the attached Agreed Order on behalf	the attached Agreed Order. I am authorized to of the entity indicated below my signature, and I d therein. I further acknowledge that the TCEQ, in materially relying on such representation.
 additional penalties, and/or attorney f Increased penalties in any future enformation. Automatic referral to the Attorney General and TCEQ seeking other relief as authorize 	ent, may result in: ory; tions submitted; eneral's Office for contempt, injunctive relief, ees, or to a collection agency; reement actions; heral's Office of any future enforcement actions;
15-	10-9-15
Signature	Date
CRECORY M MSICE Name (Printed or typed)	VP SITE MAUCEA
Authorized Representative of BASF TOTAL Petrochemicals LLC	•

Instructions: Send the original, signed Agreed Order with penalty payment to the Financial Administration Division, Revenue Operations Section at the address in Section IV, Paragraph 1 of this Agreed Order.

	•			
			v.	

Attachment A

Docket Number: 2015-1086-AIR-E SUPPLEMENTAL ENVIRONMENTAL PROJECT

Respondent:	BASF TOTAL Petrochemicals LLC
Penalty Amount:	Twenty-Six Thousand Two Hundred Fifty-One Dollars (\$26,251)
SEP Offset Amount:	Thirteen Thousand One Hundred Twenty-Five Dollars (\$13,125)
Type of SEP:	Contribution to a Third-Party Pre-Approved SEP
Third-Party Administrator:	Southeast Texas Regional Planning Commission
Project Name:	West Port Arthur Home Energy Efficiency Program - Lighthouse Program
Location of SEP:	Jefferson County

The Texas Commission on Environmental Quality ("TCEQ") agrees to offset a portion of the administrative penalty amount assessed in this Agreed Order for the Respondent to contribute to a Supplemental Environmental Project ("SEP"). The offset is equal to the SEP Offset Amount set forth above and is conditioned upon completion of the project in accordance with the terms of this Attachment A.

1. Project Description

a. Project

The Respondent shall contribute the SEP Offset Amount to the Third-Party Administrator named above. The contribution will be to the **Southeast Texas Regional Planning Commission** for the *West Port Arthur Home Energy Efficiency Program - Lighthouse Program* Project. The contribution will be used in accordance with the SEP between the Third-Party Administrator and the TCEQ (the "Project"). Specifically, the SEP Offset Amount will be used to hire a contractor to conduct initial inspections of eligible applicants' homes. The inspections will determine whether the home is in a condition suitable for weatherization and energy efficiency upgrades. Upgrades will not be completed at homes that need new roofs or significant foundation work. The contractor shall also determine what weatherization and energy efficiency upgrades are necessary and appropriate for the home and write a work plan. This contractor shall also conduct the final inspection of the home after the work is completed.

The Third-Party Administrator will conduct eligibility determinations to verify that participants own their homes and qualify as low-income. The Third-Party Administrator will also prepare all contracts with contractors and homeowners; coordinate between the contractors and the homeowners to answer questions; ensure that work is done timely and properly; and arrange for any necessary repairs to new equipment under the 12-

month warranty period after work is completed. The SEP will be done in accordance with all federal, state, and local environmental laws and regulations.

All dollars contributed will be used for the direct cost of implementing the Project, including, but not limited to supplies, materials, and equipment. Any portion of this contribution that is not spent on the specifically identified SEP may, at the discretion of the Executive Director ("ED"), be applied to another pre-approved SEP.

The Respondent's signature affixed to this Agreed Order certifies that the Respondent has no prior commitment to make this contribution and that it is being contributed solely in an effort to settle this enforcement action. The Respondent shall not profit in any manner from this SEP.

b. Environmental Benefit

Implementation of this Project will benefit air by reducing residential fuel and electricity usage for heating and cooling. These reductions, in turn, will reduce emissions of particulate matter, volatile organic compounds, and the nitrogen oxides associated with the combustion of fuel and the generation of electricity. Past energy audits have shown a 12-30% reduction in energy usages after completion of the weatherization and energy upgrades.

c. Minimum Expenditure

The Respondent shall contribute at least the SEP Offset Amount to the Third-Party Administrator and comply with all other provisions of this SEP.

2. Performance Schedule

Within 30 days after the effective date of this Agreed Order, the Respondent must contribute the SEP Offset Amount to the Third-Party Administrator. The Respondent shall make the check payable to **Southeast Texas Regional Planning Commission SEP** and shall mail the contribution with a copy of the Agreed Order to:

Southeast Texas Regional Planning Commission Attention: Pamela Lewis, Program Manager 2210 Eastex Freeway Beaumont, Texas 77703

3. Records and Reporting

Concurrent with the payment of the SEP Offset Amount, the Respondent shall provide the Enforcement SEP Coordinator with a copy of the check and transmittal letter indicating full payment of the SEP Offset Amount to the Third-Party Administrator. The Respondent shall mail a copy of the check and transmittal letter to:

Texas Commission on Environmental Quality Enforcement Division Attention: SEP Coordinator, MC 219 P.O. Box 13087 Austin, Texas 78711-3087

4. Failure to Fully Perform

If the Respondent does not perform its obligations under this Attachment A, including full expenditure of the SEP Offset Amount and submittal of the required reporting described in Sections 2 and 3 above, the ED may require immediate payment of all or part of the SEP Offset Amount.

In the event the ED determines that the Respondent failed to fully implement and complete the Project, the Respondent shall remit payment for all or a portion of the SEP Offset Amount, as determined by the ED, and as set forth in the attached Agreed Order. After receiving notice of failure to complete the SEP, the Respondent shall include the docket number of the attached Agreed Order and a note that the enclosed payment is for the reimbursement of a SEP; shall make the check payable to "Texas Commission on Environmental Quality"; and shall mail it to:

Texas Commission on Environmental Quality Litigation Division Attention: SEP Coordinator, MC 175 P.O. Box 13087 Austin, Texas 78711-3087

5. Publicity

Any public statements concerning this SEP and/or project, made by or on behalf of the Respondent must include a clear statement that **the project was performed as part of the settlement of an enforcement action brought by the TCEQ**. Such statements include advertising, public relations, and press releases.

6. Recognition

The Respondent may not seek recognition for this contribution in any other state or federal regulatory program.

7. Other SEPs by TCEQ or Other Agencies

The SEP Offset Amount identified in this Attachment A and in the attached Agreed Order has not been, and shall not be, included as a SEP for the Respondent under any other Agreed Order negotiated with the TCEQ or any other agency of the state or federal government.